



*Version 1.0*

**TECHNICAL  
NOTE**

**WILLOW® PRODUCTS RECALIBRATION  
PROCESS**



## DOCUMENT

|                    |                                          |              |            |
|--------------------|------------------------------------------|--------------|------------|
| Document ID        | UM_RF_05                                 | Version      | V1.0       |
| External reference | TN-RF-25                                 | Date         | 16/06/2021 |
| Author             | Seddik ATTIG, Technical support engineer |              |            |
|                    |                                          | Project Code |            |
| Document's name    | Wilow products recalibration process     |              |            |

## VALIDATION

| Function   | Destination   | For validation | For info |
|------------|---------------|----------------|----------|
| Writer     | Seddik ATTIG  | ✓              |          |
| Reader     | Shimon ABBADI | ✓              |          |
| Validation | Antje JACOB   |                | ✓        |

## DIFFUSION

| Function   | Destination                               | For action | For info |
|------------|-------------------------------------------|------------|----------|
| Reader n°1 | Antje JACOB, Production Manager           | ✓          |          |
| Reader n°2 | Shimon ABBADI, Embedded software engineer | ✓          |          |

## UPDATES

| Version | Date       | Auteur       | Evolution & Status                                                              |
|---------|------------|--------------|---------------------------------------------------------------------------------|
| 1.0     | 16/06/2021 | Seddik ATTIG | <ul style="list-style-type: none"> <li>First version of the document</li> </ul> |

## *Disclaimer*

The contents are confidential and any disclosure to persons other than the officers, employees, agents or subcontractors of the owner or licensee of this document, without the prior written consent of Beanair GmbH, is strictly prohibited.

Beanair makes every effort to ensure the quality of the information it makes available. Notwithstanding the foregoing, Beanair does not make any warranty as to the information contained herein, and does not accept any liability for any injury, loss or damage of any kind incurred by use of or reliance upon the information.

Beanair disclaims any and all responsibility for the application of the devices characterized in this document, and notes that the application of the device must comply with the safety standards of the applicable country, and where applicable, with the relevant wiring rules.

Beanair reserves the right to make modifications, additions and deletions to this document due to typographical errors, inaccurate information, or improvements to programs and/or equipment at any time and without notice.

Such changes will, nevertheless be incorporated into new editions of this document.

Copyright: Transmittal, reproduction, dissemination and/or editing of this document as well as utilization of its contents and communication thereof to others without express authorization are prohibited. Offenders will be held liable for payment of damages. All rights are reserved.

Copyright © Beanair GmbH 2021



# Contents

|                                                             |    |
|-------------------------------------------------------------|----|
| 1. TECHNICAL SUPPORT.....                                   | 7  |
| 2. VISUAL SYMBOLS DEFINITION.....                           | 8  |
| 3. ACRONYMS AND ABBREVIATIONS .....                         | 9  |
| 4. DOCUMENT ORGANIZATION.....                               | 10 |
| 5. BEANDEVICE® AX-3D AND AX-3DS RECALIBRATION PROCESS ..... | 11 |
| 5.1 Factory Calibration Process .....                       | 11 |
| 5.2 How often to recalibrate the BEANDEVICE®? .....         | 11 |
| 5.3 Recalibration Process.....                              | 11 |
| 6. BEANDEVICE® WILLOW® HI-INC .....                         | 15 |
| 6.1 Factory Calibration Process .....                       | 15 |
| 6.2 How often to recalibrate the BEANDEVICE®? .....         | 15 |
| 6.3 Recalibration Process.....                              | 15 |

## List of Tables

|                                                  |    |
|--------------------------------------------------|----|
| Table 1: BeanDevice Recalibration duration ..... | 11 |
| Table 2: Recalibration values calculation .....  | 13 |
| Table 3: BeanDevice Recalibration duration ..... | 15 |
| Table 4: Recalibration values calculation .....  | 17 |

## List of Figures

|                                                  |    |
|--------------------------------------------------|----|
| Figure 1: Reset settings.....                    | 11 |
| Figure 2: Obtention of 1g on the Z axis .....    | 12 |
| Figure 3: Obtention of 1g on the Y axis .....    | 12 |
| Figure 4: Obtention of the 1g on the X axis..... | 13 |
| Figure 5: Recalibration values.....              | 14 |
| Figure 6: Reset settings.....                    | 15 |
| Figure 7: Sinus table.....                       | 16 |
| Figure 8: Bringing 14° on X axis .....           | 16 |
| Figure 9: Bring 14° on the Y axis .....          | 17 |
| Figure 10: New recalibration values .....        | 18 |

## 1. TECHNICAL SUPPORT

---

For general contact, technical support, to report documentation errors and to order manuals, contact ***Beanair Technical Support Center*** (BTSC) at:

[tech-support@Beanair.com](mailto:tech-support@Beanair.com)

For detailed information about where you can buy the Beanair equipment/software or for recommendations on accessories and components visit:

[www.Beanair.com](http://www.Beanair.com)




To register for product news and announcements or for product questions contact Beanair's Technical Support Center (BTSC).

Our aim is to make this user manual as helpful as possible. Keep us informed of your comments and suggestions for improvements.

Beanair appreciates feedback from the users of our information.

## 2. VISUAL SYMBOLS DEFINITION

---

| <i>Symbols</i>                                                                    | <i>Definition</i>                                                                                                                                                                                                        |
|-----------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
|  | <b><i><u>Caution or Warning</u></i></b> – Alerts the user with important information about Beanair wireless sensor networks (WSN), if this information is not followed, the equipment /software may fail or malfunction. |
|  | <b><i><u>Danger</u></i></b> – This information <b>MUST</b> be followed if not you may damage the equipment permanently or bodily injury may occur.                                                                       |
|  | <b><i><u>Tip or Information</u></i></b> – Provides advice and suggestions that may be useful when installing Beanair Wireless Sensor Networks.                                                                           |



### 3. ACRONYMS AND ABBREVIATIONS

---

|                |                                                   |
|----------------|---------------------------------------------------|
| <i>AES</i>     | Advanced Encryption Standard                      |
| <i>CCA</i>     | Clear Channel Assessment                          |
| <i>CSMA/CA</i> | Carrier Sense Multiple Access/Collision Avoidance |
| <i>GTS</i>     | Guaranteed Time-Slot                              |
| <i>kSps</i>    | Kilo samples per second                           |
| <i>LLC</i>     | Logical Link Control                              |
| <i>LQI</i>     | Link quality indicator                            |
| <i>LDCDA</i>   | Low duty cycle data acquisition                   |
| <i>MAC</i>     | Media Access Control                              |
| <i>PAN</i>     | Personal Area Network                             |
| <i>PER</i>     | Packet error rate                                 |
| <i>RF</i>      | Radio Frequency                                   |
| <i>SD</i>      | Secure Digital                                    |
| <i>WSN</i>     | Wireless sensor Network                           |

#### 4. DOCUMENT ORGANIZATION

---

##### AX-3D & AX-3DS Recalibration Process

- Factory calibration
- How often to recalibrate the BeanDevice
- Recalibration Process

##### Hi-Inc Recalibration Process

- Factory calibration
- How often to recalibrate the BeanDevice
- Recalibration Process

## 5. BEANDEVICE® AX-3D AND AX-3DS RECALIBRATION PROCESS

### 5.1 FACTORY CALIBRATION PROCESS

A static calibration method is used to calibrate the sensor

### 5.2 HOW OFTEN TO RECALIBRATE THE BEANDEVICE®?

Depending on the operating environmental conditions, a recalibration process should be done to rectify the aging drift due to a long duration of the sensor usage and a temperature drift due to a high temperature environment.

The following table summarize how often user should recalibrate the sensor.

***Table 1: BeanDevice Recalibration duration***

| <i>BeanDevice® Willow® version</i> | <i>Operating temperature &lt; 40°C</i> | <i>Operating temperature &gt; 40°C</i> |
|------------------------------------|----------------------------------------|----------------------------------------|
| <b>BeanDevice® Willow® AX-3D</b>   | <b>6 years</b>                         | <b>3 years</b>                         |
| <b>BeanDevice® Willow® AX-3DS</b>  | <b>3 years</b>                         | <b>2 years</b>                         |


### 5.3 RECALIBRATION PROCESS

A static calibration should be done on a table using a reference accelerometer sensor or using a flat desk/table (you can use marble desk or granite desk), but make sure to use a table with a good flatness.

Then follow the instructions below

- ***First Step***


Firstly, you have to back up the previous calibration values (Ratio + Offset), then, reset ratio value to 1 and offset to 0 from the sensor calibration tab on your BeanScope® software.



***Figure 1: Reset settings***

- **Second Step**


Point the Positive Z axis to point to the ground to obtain 1g, then do the same thing with the Negative Z.




**Figure 2: Obtention of 1g on the Z axis**

Each Axis (Positive and Negative) should point to the ground to have the 1g, redo the same instructions with X and Y axis.

The best way to obtain the 1g on the X and Y axis, is to use very accurate 90° bracket.



**Figure 3: Obtention of 1g on the Y axis**



**Figure 4: Obtention of the 1g on the X axis**

- Third Step:**

Use the Recalibration Excel sheet, and put the obtained values in the blue field for each axis.



**Do not change the values in the red field otherwise you will get a faulty calibration value.**

**Table 2: Recalibration values calculation**


| X               |                   |        |        | Target X |
|-----------------|-------------------|--------|--------|----------|
| Positive X axis | Obtained +X value | Ratio  | 1.413  | 1        |
| Negative X axis | Obtained -X value | Offset | -0.079 | -1       |

**DO NOT CHANGE THESE VALUES**

**ENTER YOUR SETTINGS IN BLUE AREA**

- Fourth step:**

Enter the new obtained Ratio and offset on the red field, on the BeanScope software sensor calibration settings.



**Figure 5: Recalibration values**

Don't forget to validate.

## 6. BEANDEVICE® WILOW® HI-INC

### 6.1 FACTORY CALIBRATION PROCESS

The calibration procedure is based on a side-by-side comparison with a reference tilt meter. For better measurement stability, the two tilt meters are mounted on a sinus table.

### 6.2 HOW OFTEN TO RECALIBRATE THE BEANDEVICE®?

Depending on the operating environmental conditions, a recalibration process should be done to rectify the aging drift due to a long duration of the sensor usage and a temperature drift due to a high temperature environment.

The following table summarize how often user should recalibrate the sensor.

*Table 3: BeanDevice Recalibration duration*

| <i>BeanDevice® Wilow® version</i> | <i>Operating temperature &lt; 40°C</i> | <i>Operating temperature &gt; 40°C</i> |
|-----------------------------------|----------------------------------------|----------------------------------------|
| BeanDevice® Hi-Inc.               | 6 years                                | 3 years                                |


### 6.3 RECALIBRATION PROCESS

A static calibration should be done using a granite desk a sinus table and which is already fixed on a preconfigured position.

Then follow the instructions below

- ***First Step***

Firstly, you have to back up the previous calibration values (Ratio + Offset), then, reset ratio value to 1 and offset to 0 from the sensor calibration tab on your BeanScope® software.




*Figure 6: Reset settings*




- **Second Step**

Put the BeanDevice Hi-Inc on the sinus table on the +X axis to obtain 14° (just an example, you can predefine any other angle), then reverse the BeanDevice on the -X axis.




*Figure 7: Sinus table*



*Figure 8: Bringing 14° on X axis*



Redo the same instructions with Y axis.



**Figure 9: Bring 14° on the Y axis**

- **Third Step:**

Use the Recalibration Excel sheet, and put the obtained values in the blue field for each axis.



**Do not change the values in the red and yellow fields otherwise you will get a faulty calibration value.**

**Table 4: Recalibration values calculation**

| X             |         |        |       |
|---------------|---------|--------|-------|
| Positive axis | 14.058  | Ratio  | 1     |
| Negative axis | -14.002 | Offset | 0.000 |

- **Fourth step:**

Enter the new obtained the offset on the yellow field, on the BeanScope software sensor calibration settings.

The ratio value is always equal to 1, it doesn't change ever.

| X             |         |        |       |
|---------------|---------|--------|-------|
| Positive axis | 14.058  | Ratio  | 1     |
| Negative axis | -14.002 | Offset | 0.000 |

| Custom display | Notes | Measurement conditioning calibration | MQTT Conf | L |
|----------------|-------|--------------------------------------|-----------|---|
| Calibration    |       |                                      |           |   |
| Ratio :        | 1     | 1                                    |           |   |
| Offset :       | 0     | 0                                    | Validate  |   |

**Figure 10: New recalibration values**

Don't forget to validate.