

Displacement Sensor Integration with BeanDevice[®] AN-420

March 2017 - Youssef Shahine Technical Support Engineer tech-support@beanair.com



Sensor Wiring code (1/2)

0-		-	_	
Ca	pu	О	n	
	-	-	_	_

- PIN1 (Pwr+): Sensor power supply
- PIN4 (SI): signal input
- PIN2 : Not used, must be
- connected to Gnd
- PIN3 (Gnd): Electrical Ground





Figure 13: M12-4pins Plug Wiring code (sensor side)



Red wire must be connected to **PIN1 Blue** wire must be connected to **PIN4**



<u>For more info about the sensor wiring code :</u> http://www.wireless-iot.beanair.com/files/UM-RF-02-ENG-ProcessSensor-Wireless-DAQ.pdf Page 30



Sensor Wiring code (2/2)



LVDT sensor integrated with M12-4Pins Plug



LVDT sensor mounted on the BeanDevice® AN-420

BeanAir Sensor configuration from BeanScape® software

Recommended Voltage : 12V Sensor warm-up time : 40ms

Sensor profile				Custom display	Notes	Configuration	Measurement conditionning calibration	Log config.	
General information					Sensor pre-processing time configuration H2 0.4353				
Type : SENSOR_TYPE	Excitation :	12.000	V	Period :			ms Validate L1 25.565		
Ref: 0	Pre-proc. :	40	ms	Excitation vo	Itage cor	figuration			
Label : Ch_mA_0				Power			V Validate		
Technology : AN 4-20 mA				Mesurement da	ta				
State : On									
				Value 24.9	899	Date	12/03/2017 17:36:37		

<u>Use the conversion Assistant:</u> 4 mA => 20 mm (sensor probe fully out) 20 mA => 0 mm (sensor probe fully in)

Custom dis	play Notes	Configurat	ion I	Measurement conditionning calibration	Log config.			
Ratio :	1		Offset	: 0				
Unit :	mA		Туре	: SENSOR_TYPE				
Ref :	SENSOR_R	EF	Label	: Ch_mA_0				
	Conversion Assistant Validate							
Mesureme	nt data							
Value	-0.0046		Date	12/03/2017 17:35:17				

Jn	it Convers	sion Assistant	_		×		
	Linear Co	Input :	Output :				
	Value 1	4 mA	20	mm	Ŧ		
	Value 2	20 mA		mm			
		Target Unit :	mm	~			
OK Cancel							